HPH spol.s r.o. Čáslavská 234 CZ284 01 Kutná Hora Czech Republic Tel/Fax 00420-327 512633 e-mail : <i>info@hph.cz</i>	Service bulletin	No.: G304SJet – 15a)
Туре:	Type Certificate No.:EASA.A.030Model:Glasfügel 304S JetSerial No.:all	
Subject:	Editorial update of AFM. Update of maintenance, repair and overhaul procedures.	
Urgency:	Before next Annual inspection or before repair of the TJ-42 engine.	
Refer. documents:	doc. no.: G304Sjet/AFMSupp - AFM Supplement for the Sailplane Glasflügel 304S Jet , 12/23	
	doc. no.: 304SJet/MMSupp - Maintenance and Repair Manual for the Sailplane Glasflügel 304S Jet, 04/25	
Reason:	 For maintenance of the engine TJ-42 (approved as a part of the sailplane): procedures related to airworthiness limited parts were approved by EASA instructions for maintenance actions were updated information regarding to the engine damage identification and repairs were updated 	
	For operation of the Glasfügel 304S Jet: - Vy designation was corrected	
Action	Replace affected pages of the manuals (see Material).	
Material:	doc. no.: G304Sjet/AFMSupp pages: 0-1; 0-2; 2-3	
	doc. no.: 304SJet/MMSupp pages: ii; iii; iv; v; 3-1 to 3-9; 4-0; 4-1	
Weight and balance:	Not affected	
Remarks	All maintenance work must be carried out and certified by qualified and authorized personnel.	
	Owner covers the expenses of the action.	
Page 1/1		
HPH, spol.s.r.o. Čáslavská 234 CZ284 01 Kutná Hora Czech republic	The technical content of this document is approved authority of EASA (ref. approval no. 10087116) and produced in accordance with alternative procedure EASA.AP198.	have been lesued by